




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	28	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	5712	<b>Street Prefix:</b>		<b>Street Name:</b>	Rusk	<b>Street Type:</b>	AVE
<b>Source Type:</b>	02= Service Line	<b>Location:</b>		1=Paved Concrete	<b>Severity:</b>		
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	25				
<b>Comments:</b>	sidewalk						

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_A\A\_2004\_0817Image0002.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 28

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\28.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	28	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2513		Crest	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	
<b>Comments:</b>	clean out - side of yard			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_A\A\_2004\_0817Image0003.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 28

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\28.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY


Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	28	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5705		Rusk	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	50	
<b>Comments:</b>	Frt. Yrd. Clean out			

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 1

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_B\B\_2004\_0817Image0001.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 28

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\28.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	28	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5709		Rusk	AVE

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	100	
<b>Comments:</b>	front yard - 4 areas			

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_B\B\_2004\_0817Image0002.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 28

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\28.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	28	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>	
5711		Rusk	AVE	
<b>Source Type:</b>	18= Other	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	
<b>Comments:</b>	foundation			

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_B\B\_2004\_0817Image0003.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 28

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\28.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY


Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	28	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5715		Rusk	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	100	
<b>Comments:</b>	fr. Yrd.			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 4

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_B\B\_2004\_0817Image0004.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 28

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\28.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	28	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	5	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	


<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5719		Rusk	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
---------------------	--------------	------------------	-------------	------------------

<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	75
----------------	-----------	-----------------------	----

**Comments:** back yard

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_B\B\_2004\_0817Image0005.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 28

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\28.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


<b>Unique Test ID</b>	28	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	6	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2505		Crest	ROAD

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	100	

**Comments:** unknown defect in back yrd.

## SMOKE TEST PHOTOS



**Photo No:** 6

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Retakes\B\B\_2004\_0817Image0006.JPG

**Image Status:** Image found and displayed.



**Photo No:** 4

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Retakes\T\TID28-B6\_2005\_0523Image004.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 28

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\28.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	29	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2600		Whitney	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 4

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_A\A\_2004\_0817Image0004.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 29

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\29.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


<b>Unique Test ID</b>	29	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5700		Rusk	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_A\A\_2004\_0817Image0005.JPG

**Image Status:** Image found and displayed.



**Photo No:** 9

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_A\A\_2004\_0817Image0009.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

29

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\29.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	29	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2504		Whitney	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 6

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_A\A\_2004\_0817Image0006.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 29

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\29.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	29	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2502		Whitney	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 7

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0817-2004\T-1\PLAYER\_A\A\_2004\_0817Image0007.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 29

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\29.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	29	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	5	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2502		Whitney	AVE

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	21	

**Comments:** Defects from sewer main to house

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 8

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_A\A\_2004\_0817Image0008.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 29

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\29.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	29	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	6	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2503		Whitney	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	25	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 10

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_A\A\_2004\_0817Image0010.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 29

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\29.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY


Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	29	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	7	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2505		Whitney	AVE

<b>Source Type:</b>	14= Catch Basin	<b>Location:</b>	6=Curb	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	5000	
<b>Comments:</b>	inlet			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 11

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_A\A\_2004\_0817Image0011.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 29

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\29.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


<b>Unique Test ID</b>	29	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	8	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2505		Whitney	AVE

<b>Source Type:</b>	14= Catch Basin	<b>Location:</b>	6=Curb	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	5000	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 11

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_A\A\_2004\_0817Image0011.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 29

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\29.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	29	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2605		Whitney	AVE

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	75	
<b>Comments:</b>	driveway edge			

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 7

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_B\B\_2004\_0817Image0007.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 29

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\29.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


<b>Unique Test ID</b>	29	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2505		Whitney	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	75	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 9

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_B\B\_2004\_0817Image0009.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 29

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\29.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	29	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2505		Whitney	AVE

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	75	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 9

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0817-2004\T-1\PLAYER\_B\B\_2004\_0817Image0009.JPG

**Image Status:** Image found and displayed.



**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Retakes\UTID29-B3\2005\_0523Image003.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 29

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\29.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	29	<b>Date:</b>	8/17/2004	<b>MeterBasin:</b>	01_WR18
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	4	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>	
2600		Whitney	AVE	
<b>Source Type:</b>	14= Catch Basin	<b>Location:</b>	6=Curb	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	4500	
<b>Comments:</b>	inlet drain			

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 10

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0817-2004\T-1\PLAYER\_B\B\_2004\_0817Image0010.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 29

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\29.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.